BRUHAT BANGALORE MAHANAGARA PALIKE

INSPECTION REPORT

Division: Hebbal — Sub Division: Hebbal / JC Nagar

Ward No. 18

Sl No	Descriptions	Details	Remarks
1	Name of the work	Construction of drain and culverts in Doddappaiah Layout inWard NO. 18	
2	Administrative Sanction No and Date	EE(H)AS/93/13-14 dated: 30/10/2013	
3	Technical Sanction No and Date	EE(H)TS/98/13-14 dated: 30/10/2013	
4	Job Number, date and P-code	018-14-000009	
5	Estimate Cost (Rs in Lakhs)	Rs. 10.00 Lakhs	
6	Tender (or) Direct Entrustment to KRIDL	Tender	
7	If tendered, Tender notification number date and publication in Daily news paper	EE/H/TEND/09/13-14 dated:	
8	Tender Approval Details	Rs. 863544.14	
9	Date of work order and number	EE/H/AE/WO/178/13-14 dated: 10/02/2014	
10	Stipulated time and completion	9/4/2014	
11	Actual date of completion	30/04/2014	
12	Delay if any	"Nil"	
13	Reasons for delay	-	
14	Payment made till date	Payment due	
15	Pending bill details status of work	Completed	
16	Quality test report	Sumitted	
17	Photographs of the completed works	Submitted	
18	M.B. No and page number	56/11-12 P-5579-83	
19	Bill form	Submitted	
20	Remarks- Recommendations of the inspection team – Name / Mobile No / E-Mail	Certified that the above work is inspected on 09-03-2016, Verified MB and bill file which are technically chaFC. work is satisfactory. Bill payment may be released.	

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

G. R. Hiremath EE Retd)
District Quality Monitor

G. R. Hiremath EE (Retd)
District Quality Monitor
Bruhat Bangalore Mahanagara Palike